



## M12 PCB 孔位分布图 & 钻孔尺寸

### PCB 孔位分布图


#### M12 公头连接器




(Pin OD:  $\Phi$  0.8)  
3P/4P/5P




(Pin OD:  $\Phi$  1.0)  
3P/4P/5P



(Pin OD:  $\Phi$  0.8)  
8P




(Pin OD:  $\Phi$  0.6)  
12P




(Pin OD:  $\Phi$  0.6)  
17P

建议 PCB 孔位分布图


#### M12 母头连接器




(Pin OD:  $\Phi$  0.8)  
3P/4P/5P




(Pin OD:  $\Phi$  1.0)  
3P/4P/5P



(Pin OD:  $\Phi$  0.8)  
8P



(Pin OD:  $\Phi$  0.6)  
12P




(Pin OD:  $\Phi$  0.6)  
17P


建议 PCB 孔位分布图

#### M12 C-Coding 连接器


##### 公头连接器




3Pin



4Pin




5Pin




6Pin


##### 母连接器




3Pin



4Pin



5Pin



6Pin

#### M12 快锁式连接器

